

Photo 1. Site 1. Historic meander in right overbank (photo is looking upstream)



Photo 2. Site 2. Historic meander



Photo 3. Site 3. Over-widened stream reach



Photo 4. Site 4. Unvegetated overbanks contributing to stream



Photo 5. Site 5. Minor to moderate erosion on steep bank



Photo 6. Site 6. Erosion around bridge abutments



Photo 7. *Site 8.* Erosion around bridge abutments



Photo 8. *Site 9.* Erosion around bridge abutments



Photo 9. *Site 10.* Incised stream bed



Photo 10. *Site 11.* Minor to moderate erosion on outside of bank meander



Photo 11. *Site 12.* Minor to moderate erosion on stream bank



Photo 12. *Site 13.* Minor to moderate erosion on outside of bank meander



Photo 13. *Site 14.* Eroded culvert outfall



Photo 14. *Site 15.* Minor to moderate erosion on outside of stream bend



Photo 15. *Site 16.* Significant erosion on outside of stream bend



Photo 16. *Site 17.* Minor to moderate erosion on outside of stream bend



Photo 17. Site 18. Large woody debris in stream



Photo 18. Site 19. Large woody debris in stream



Photo 19. *Site 20.* Meander in process of being cut off



Photo 20. *Site 21.* Over-widened stream reach

